

Inspection Report

Report No.: XYDW-140609
Supplier : XY-GLOBAL

Inspection Date: 3rd July, 2014
Inspector: Leo

Inspection only for: PO : XYDW-140609 Item No. XY33AH004	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH004	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Date	3rd July 2014	Inspector	Leo	Inspection Result	PASS
PO No.	XYDW-140609	Item No.	XY33AH004	Lot No.	10000PCS
Inspection Type	100% Inspection	Inspection Method	Visual Inspection	Inspection Location	Factory
Inspection Item	1. Appearance: No defect found. 2. Dimension: No defect found. 3. Assembly: No defect found.				
Inspection Result	All items passed inspection.				
Inspector	Leo				
Signature	[Signature]				
Date	3rd July 2014				

100% Inspection Report

Lot No.	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	

100% Inspection Report

5. Product:

6. report

[illegible]