XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYSJ-140713
Supplier : **XY-GLOBAL**

Inspection Date:17th Aug, 2014
Inspector: Leo

Inspection only for:	Inspection Result:
PO . XYSJ-140713 Item No. XY11KA009	**PASS**

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11KA009	**20000PCS**	5% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:



序	公	日	日	日	日	日	日
号	称	期	公	公	测	差	结
1	-75.296	0.050	0.050	-75.296	0.000	0.000	
2	0.021	0.050	0.050	0.021	0.000	0.000	
3	2.553	0.050	0.050	2.553	0.000	0.000	

序	公	日	日	日	日	日	日
号	称	期	公	公	测	差	结
1	-81.017	0.050	0.050	-81.017	0.000	0.000	
2	-0.029	0.050	0.050	-0.029	0.000	0.000	
3	6.353	0.050	0.050	6.353	0.000	0.000	

序	公	日	日	日	日	日	日
号	称	期	公	公	测	差	结
1	-81.028	0.050	0.050	-81.028	0.000	0.000	
2	153.376	0.050	0.050	153.376	0.000	0.000	
3	8.410	0.050	0.050	8.410	0.000	0.000	

序	公	日	日	日	日	日	日
号	称	期	公	公	测	差	结
1	80.862	0.050	0.050	80.862	0.000	0.000	
2	153.416	0.050	0.050	153.416	0.000	0.000	
3	6.269	0.050	0.050	6.269	0.000	0.000	

序	公	日	日	日	日	日	日
号	称	期	公	公	测	差	结
1	80.893	0.050	0.050	80.893	0.000	0.000	
2	-0.582	0.050	0.050	-0.582	0.000	0.000	
3	6.227	0.050	0.050	6.227	0.000	0.000	

序	公	日	日	日	日	日	日
号	称	期	公	公	测	差	结
1	-57.482	0.050	0.050	-57.482	0.000	0.000	
2	-8.372	0.050	0.050	-8.372	0.000	0.000	
3	2.563	0.050	0.050	2.563	0.000	0.000	

序	公	日	日	日	日	日	日
号	称	期	公	公	测	差	结
1	0.529	0.050	0.050	0.529	0.000	0.000	
2	-46.216	0.050	0.050	-46.216	0.000	0.000	
3	2.079	0.050	0.050	2.079	0.000	0.000	

序	公	日	日	日	日	日	日
号	称	期	公	公	测	差	结
1	0.527	0.050	0.050	0.527	0.000	0.000	
2	-35.413	0.050	0.050	-35.413	0.000	0.000	
3	2.094	0.050	0.050	2.094	0.000	0.000	

6. The test report

□□□□□□□□□	□□□□□ □□□□□□ □□□□□□□ □□□□□□□ □□□□□□ □□□□□□□ □□□□□□□□□ □□□□□□□ □□□□ □□□□ □□□□□ □□□ □□□□ □□□□□ OEM □□□□ □□□□□ □□□□ □□□□□□□□□□ □□□□ □□□□ □□□□ □□□□□ □□□□□□□
□□□□□□□	□□□□□□□□□□□ ADC12□ A380 □□□
□□□□□□	□□□□□□ □□□□ □□□ □□□□□□□□
□□□□□□□□ □□□□□□□□□	□□□□□□ □□□□□□ □□□□□□□□□□□ □□□□□□□ □□□□□□□□ □□□□□□□ □□□□□ □□□□□□□ □□□□□□□ □□□□□ □□□ □□□□
□□□□□□□□	□□□□□□ □□□□□□□□□ □□□□ □□ □□□□□□□ □□□□
□□□□□□□□ □□□□□□	CNC □□□□□ □□□ □□□□ □□□ □□□□□ □□□□□□ □□□ □□□□ □□□ □□□□ □□□ □□□□□□□ □□□□□ CNC □□□ □□□ □□□
□□□□ □□□□□	□□□□□□□□□ □□□□□□ □□□□□□□ □□□□□ gague□ □□□□□□□□ □□□□□□□ □□□□□□□□ □□□□□□□ □□□□□ □□□□□□□□ □□□□□ □□□□□□□ □□□□ □□□□□□□□□ □□□□ □□□□□□□□ □□□□□□□ □□□□□□□□□ □□□□ □□□ □□□□□ □□□□□□□ □□□□ □□□ □□□□□□□ □□□□□□□ □□□□□□□□ □□□□□ □□□□□□□ □□□□□□□
□□□	□□□□□□□ □□□□
□□□□□□□ / □□□□□	+/- 0.01MM
□□□	T / T 50 □ □□□□□ □50 □□□□□□ T / T □□□□□ □□ □□□□□□ □□□.
□□□□□□□ □□□□	CNC □□□□□□□ □□□□□ □□□□□ □□□□□□ □□□□□□□□ □□□□□□□ □□□□□ □□□□□□□□□ □□□□□□□ □□□□ □□□ □□□□□□ □□□□□ □□□□ □□□□□□ □□□□□□□ □□□□□ □□□□ □□□□□□□□
□□□□□	□□□□□□□□ □□□□□□□□□□ □□□□□□□□□ □□□□□ □□□□□□□ □□□□□□□□ □□□□ □□□□□ □□□□□□□ □□□□□□□□ □□□□ □□□□ □□□□ □□□□ □□□□□□□□□□ □□□□ □□□□□□□□ □□ □□□□□□ □□□□□□□□□□□
□□□□□□□	□□□□□ □□□□□
□□□□□	20-25 □□□ □□□□ T / T 50□ □□□□□□□□ □□
□□□□□□□□□ □□□□□□□	□□□□□□ □□□□□□□□□□ □□□□
1.Name: □□□□□□ □□□ OEM □□□□□ □□□□ □□□□ □□□□□□□□□□	
2.Process: □□□□□ □□□□□□ □□□□□□□□ □□□□□□□ □□□□□ □□□□ □□□□□□□□□□	
3.Material: □□□□□□□□□□ □□ ADC12□ A380 □□□	
4.Surface □□□ □□□□□□ □□□□□□ □□□□□□ □□□□□□□ □□□□□□□□ □□□□□ □□□□□□ :□□□□□	
5.Tolerance: 0.01 -/+ □□□ □□□ □□ □□□□MM	
6 □□□□□□.Quality: 100□ □□□□□□□	
7.Specification: OEM □□□□□□□□ □□□□□ □□ □□□□ □□□□□	
8. □□□□□□□□ □□ □□□□□ 30-25 :□□□□□□□ □□□ □□□□.	
9. □□□□□□□ □□□□□□□□□ □□□□□□□□□□□ □□□□ □□□□ □□□□□□□□□□ □□□ :□□□□□□□ accessoried □□□ □□□□□□□□ □□□□ □□□□	
10. □□□□ □□□□□□□□□□ □□□□□□□ □□□□□□□□ :□□□□□□□□ AUSTRIAL□ □□□□□□ □□□□□□□□ □□□□□□□	
11. □□□□□: ISO 9001	
□□□□ □□□□□	
1. 10 □□□□□□ □□□□□ □□ □□□□□□ □□ □□□□	
2. □□□□□ □□□□□□ □□□□□ □□□□	
3. □□ kindls □□ sureface □□□ finishment □□ abailable	
4. □□□□□□□ □□□□□□□ □□□□□ □□□□	
5. □□□□□□ □□□□□ □□ □□□□□□□ □□□□	
6. □□□□□ □□□□	
7. □□□□□□ □□□□□ □□□□ □□□ □□□□□□□ □□ □□□□ □□□□□	
□□□□□□□	
□□□□□□ □ □□□□□ □□□□ :□□□□□□ □□□□□ □□□□ □□□□ □□□□□□□□□□	
□□□□□□□□ □□□□□□□ :□□□□□□□ □□□□□ □□□□ □□□□ □□□□□□□□□□	
□□□□□ □□□□□ □□□□ □□□□ □□□□□□□□□□: ISO9001	
□□□□□□ □□□□ □□□□□□ :□□□□□□ □□□□□ □□□□ □□□□ □□□□□□□□□□	
□□□□□ □□□□ □□ □□□□ □□□□ □□□□□□□□□□ □□□ OEM	

Safety is our serious job for our worker and engineer team