

## Inspection Report

**Report No.:** XYSJ-140716

**Supplier :** XY-GLOBAL

**Inspection Date:** 25<sup>th</sup> Aug, 2014

**Inspector: Leo**

|                                                                |                                   |
|----------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYSJ-140716    Item No. XY11KA012 | <u>Inspection Result:</u><br>PASS |
|----------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY11KA012   | 33000PCS      | 5% inspection | 0pcs         | No failure          | 33000pcs        |

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

## Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



## 2. Product



3. Product



4 Product



5. Product:

[illegible]

## 6. The test report

[illegible]

## Safety is our serious job for our worker and engineer team

