

0000000000 000000 ADC12 000000000000 00000000 0000 0000 000000

Inspection Report

Report No.: XYS-130519
Supplier : XY-GLOBAL

Inspection Date: 14th Jun, 2013
Inspector: Leo

Inspection only for: PO . XYS-130519 Item No.XY-130203	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-130203	500PCS	5% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product




3. Product



4 Product



5. Product:



6. Product:

[illegible]