

Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11KA001	18000PCS	5% inspection	0pcs	No failure	18000pcs

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. The test report

[illegible]

Safety is our serious job for our worker and engineer team

