

Inspection Report

Report No.: XYLA-150310

Supplier : XY-GLOBAL

Inspection Date: 18th Apr, 2015

Inspector: Leo

Inspection only for:	Inspection Result:
PO : XYLA-150310 Item No. XY31PC007	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC007	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

Item	Spec	Unit	Value	Unit	Value	Unit	Value
1	1.1	mm	1.1	mm	1.1	mm	1.1
2	2.1	mm	2.1	mm	2.1	mm	2.1
3	3.1	mm	3.1	mm	3.1	mm	3.1
4	4.1	mm	4.1	mm	4.1	mm	4.1
5	5.1	mm	5.1	mm	5.1	mm	5.1
6	6.1	mm	6.1	mm	6.1	mm	6.1
7	7.1	mm	7.1	mm	7.1	mm	7.1
8	8.1	mm	8.1	mm	8.1	mm	8.1
9	9.1	mm	9.1	mm	9.1	mm	9.1
10	10.1	mm	10.1	mm	10.1	mm	10.1
11	11.1	mm	11.1	mm	11.1	mm	11.1
12	12.1	mm	12.1	mm	12.1	mm	12.1
13	13.1	mm	13.1	mm	13.1	mm	13.1
14	14.1	mm	14.1	mm	14.1	mm	14.1
15	15.1	mm	15.1	mm	15.1	mm	15.1
16	16.1	mm	16.1	mm	16.1	mm	16.1
17	17.1	mm	17.1	mm	17.1	mm	17.1
18	18.1	mm	18.1	mm	18.1	mm	18.1
19	19.1	mm	19.1	mm	19.1	mm	19.1
20	20.1	mm	20.1	mm	20.1	mm	20.1
21	21.1	mm	21.1	mm	21.1	mm	21.1
22	22.1	mm	22.1	mm	22.1	mm	22.1
23	23.1	mm	23.1	mm	23.1	mm	23.1
24	24.1	mm	24.1	mm	24.1	mm	24.1
25	25.1	mm	25.1	mm	25.1	mm	25.1
26	26.1	mm	26.1	mm	26.1	mm	26.1
27	27.1	mm	27.1	mm	27.1	mm	27.1
28	28.1	mm	28.1	mm	28.1	mm	28.1
29	29.1	mm	29.1	mm	29.1	mm	29.1
30	30.1	mm	30.1	mm	30.1	mm	30.1
31	31.1	mm	31.1	mm	31.1	mm	31.1
32	32.1	mm	32.1	mm	32.1	mm	32.1
33	33.1	mm	33.1	mm	33.1	mm	33.1
34	34.1	mm	34.1	mm	34.1	mm	34.1
35	35.1	mm	35.1	mm	35.1	mm	35.1
36	36.1	mm	36.1	mm	36.1	mm	36.1
37	37.1	mm	37.1	mm	37.1	mm	37.1
38	38.1	mm	38.1	mm	38.1	mm	38.1
39	39.1	mm	39.1	mm	39.1	mm	39.1
40	40.1	mm	40.1	mm	40.1	mm	40.1
41	41.1	mm	41.1	mm	41.1	mm	41.1
42	42.1	mm	42.1	mm	42.1	mm	42.1
43	43.1	mm	43.1	mm	43.1	mm	43.1
44	44.1	mm	44.1	mm	44.1	mm	44.1
45	45.1	mm	45.1	mm	45.1	mm	45.1
46	46.1	mm	46.1	mm	46.1	mm	46.1
47	47.1	mm	47.1	mm	47.1	mm	47.1
48	48.1	mm	48.1	mm	48.1	mm	48.1
49	49.1	mm	49.1	mm	49.1	mm	49.1
50	50.1	mm	50.1	mm	50.1	mm	50.1
51	51.1	mm	51.1	mm	51.1	mm	51.1
52	52.1	mm	52.1	mm	52.1	mm	52.1
53	53.1	mm	53.1	mm	53.1	mm	53.1
54	54.1	mm	54.1	mm	54.1	mm	54.1
55	55.1	mm	55.1	mm	55.1	mm	55.1
56	56.1	mm	56.1	mm	56.1	mm	56.1
57	57.1	mm	57.1	mm	57.1	mm	57.1
58	58.1	mm	58.1	mm	58.1	mm	58.1
59	59.1	mm	59.1	mm	59.1	mm	59.1
60	60.1	mm	60.1	mm	60.1	mm	60.1
61	61.1	mm	61.1	mm	61.1	mm	61.1
62	62.1	mm	62.1	mm	62.1	mm	62.1
63	63.1	mm	63.1	mm	63.1	mm	63.1
64	64.1	mm	64.1	mm	64.1	mm	64.1
65	65.1	mm	65.1	mm	65.1	mm	65.1
66	66.1	mm	66.1	mm	66.1	mm	66.1
67	67.1	mm	67.1	mm	67.1	mm	67.1
68	68.1	mm	68.1	mm	68.1	mm	68.1
69	69.1	mm	69.1	mm	69.1	mm	69.1
70	70.1	mm	70.1	mm	70.1	mm	70.1
71	71.1	mm	71.1	mm	71.1	mm	71.1
72	72.1	mm	72.1	mm	72.1	mm	72.1
73	73.1	mm	73.1	mm	73.1	mm	73.1
74	74.1	mm	74.1	mm	74.1	mm	74.1
75	75.1	mm	75.1	mm	75.1	mm	75.1
76	76.1	mm	76.1	mm	76.1	mm	76.1
77	77.1	mm	77.1	mm	77.1	mm	77.1
78	78.1	mm	78.1	mm	78.1	mm	78.1
79	79.1	mm	79.1	mm	79.1	mm	79.1
80	80.1	mm	80.1	mm	80.1	mm	80.1
81	81.1	mm	81.1	mm	81.1	mm	81.1
82	82.1	mm	82.1	mm	82.1	mm	82.1
83	83.1	mm	83.1	mm	83.1	mm	83.1
84	84.1	mm	84.1	mm	84.1	mm	84.1
85	85.1	mm	85.1	mm	85.1	mm	85.1
86	86.1	mm	86.1	mm	86.1	mm	86.1
87	87.1	mm	87.1	mm	87.1	mm	87.1
88	88.1	mm	88.1	mm	88.1	mm	88.1
89	89.1	mm	89.1	mm	89.1	mm	89.1
90	90.1	mm	90.1	mm	90.1	mm	90.1
91	91.1	mm	91.1	mm	91.1	mm	91.1
92	92.1	mm	92.1	mm	92.1	mm	92.1
93	93.1	mm	93.1	mm	93.1	mm	93.1
94	94.1	mm	94.1	mm	94.1	mm	94.1
95	95.1	mm	95.1	mm	95.1	mm	95.1
96	96.1	mm	96.1	mm	96.1	mm	96.1
97	97.1	mm	97.1	mm	97.1	mm	97.1
98	98.1	mm	98.1	mm	98.1	mm	98.1
99	99.1	mm	99.1	mm	99.1	mm	99.1
100	100.1	mm	100.1	mm	100.1	mm	100.1

6. report

[illegible]

Safety is our serious job for our worker and engineer team

