

□□□□□□ □□□□ □□□□ 6061 □□



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYA-130831&XYA-130901

Inspection Date: 11th Sep-, 2013



Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for: PO . XYA-130831&XYA-130901 Item No.400-01-038/400-01-075	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-01-038	432PCS	7% inspection	0pcs	No failure	432pcs
400-01-075	150PCS	7% inspection	0pcs	No failure	150pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:400-01-075	4. Product:400-01-075
	
5. Product :400-01-075	6. Product: 400-01-075

