

Inspection Report

Report No.: XYI-140324
Supplier : XY-GLOBAL

Inspection Date: 19th Apr, 2014
Inspector: Leo

Inspection only for: PO : XYI-140324 Item No.144031	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
144031	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing




2. Product



3. Product



4 Product



5. Product:

The screenshot shows a detailed measurement report with columns for feature names, dimensions, and tolerances. It includes data for multiple features, likely corresponding to the dimensions of the plastic component shown in the other photos.

6. Report:

[illegible]