

Inspection Report

Report No.: XYDA-150322
Supplier : XY-GLOBAL

Inspection Date: 15th Apr, 2015
Inspector: Leo

Inspection only for: PO : XYDA-150322 Item No. XY31CY038	Inspection Result: PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY038	55000PCS	1% inspection	0pcs	No failure	55000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Drawn by	Product Type	Inspection Date
JZ	六角螺栓	2015.04.15
Drawn Date	Drawn by	Inspection Date
2015.04.15	Leo	2015.04.15
Inspection Result: PASS		
Inspection Summary: No failure		
Inspection Details: 1. 外观: 无缺陷; 2. 尺寸: 符合; 3. 装配: 合格		
Inspection Conclusion: 合格		
Inspection Signatures: 检验员: Leo; 审核员: JZ		

5. Product:

6. report

1.Name: 2.Process: 3.Material: 4.Surface 5.Tolerance: 6 7.Specification: 8. 9. 10. 11. 	1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11.
---	---