

Inspection Report

Report No.: XYN-130822

Supplier : XY-GLOBAL

Inspection Date:14th Sep-, 2013

Inspector:LEO

Inspection only for: PO . XYN-130822 Item No.1402310	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1402310	2000PCS	1% inspection	0pcs	No failure	2000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]