



XY Electronics Technology Co., Ltd

## Inspection Report

Report No.: XYK-1308023

Supplier : XY-GLOBAL

Inspection Date: 14<sup>th</sup> Sep-, 2013

Inspector: LEO

|                                                            |                                   |
|------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYK-130823    Item No.1400210 | <u>Inspection Result:</u><br>PASS |
|------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 1400210     | 8000PCS       | 1% inspection | 0pcs         | No failure          | 8000pcs         |

### Appearance Inspection :

No failure,

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure

### Inspection Summary

The inspection sample plan is 100% inspection.

### Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]