

Inspection Report

Report No.: XYKS-140612

Supplier : XY-GLOBAL

Inspection Date: 10th July, 2014

Inspector: Leo

Inspection only for:	Inspection Result:
PO : XYKS-140612 Item No. XY31SY56	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY56	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市嘉朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Item	Inspection Method	Inspection Result	Inspection Date	Inspector
1. Appearance	Visual	OK	2014.07.10	Leo
2. Dimension	Caliper	OK	2014.07.10	Leo
3. Material	Visual	OK	2014.07.10	Leo
4. Function	Test	OK	2014.07.10	Leo
5. Packaging	Visual	OK	2014.07.10	Leo
6. Report	Visual	OK	2014.07.10	Leo

5. Product:

6. report

[illegible]

Safety is our serious job for our worker and engineer team

