

Inspection Report

Report No.: XYD-130825
Supplier : XY-GLOBAL

Inspection Date: 13th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYD-130825 Item No. Gear	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Gear	500SET	5% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 50pcs inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]