

## Inspection Report

Report No.: XYK-131011  
Supplier : XY-GLOBAL

Inspection Date: 29<sup>th</sup> Oct-, 2013  
Inspector: LEO

|                                                                      |                            |
|----------------------------------------------------------------------|----------------------------|
| Inspection only for:<br>PO . XYK-131011 Item No. Aluminum alloy bolt | Inspection Result:<br>PASS |
|----------------------------------------------------------------------|----------------------------|

| Description         | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|---------------------|---------------|---------------|--------------|---------------------|-----------------|
| Aluminum alloy bolt | 3000SET       | 5% inspection | 0pcs         | No failure          | 3000SET         |

### Appearance Inspection :

No failure,

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure

### Inspection Summary

The inspection sample plan is 5% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]