

Inspection Report

Report No.: XYKS-140608
Supplier : XY-GLOBAL

Inspection Date: 5th July, 2014
Inspector: Leo

Inspection only for: PO : XYKS-140608 Item No. XY31SY52	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY52	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Order No.	XYKS-140608	Product Name	XY31SY52	Inspection Date	2014.07.05
Part No.	XY31SY52	Lot Number	140608-001	Inspection Time	14:00:00
Inspector	Leo	Inspector	Leo	Inspector	Leo

1. General Inspection: The product is in good condition, no obvious defects found.

2. Dimensional Inspection: The product dimensions are within the specified range.

3. Appearance Inspection: The product surface is clean, no obvious defects found.

4. Assembly Test: The product is assembled correctly, no obvious defects found.

5. Conclusion: The product is in good condition, no obvious defects found.

6. Remarks: The product is in good condition, no obvious defects found.

5. Product:

6. report

[illegible]

Safety is our serious job for our worker and engineer team

