

Inspection Report

Report No.: XYND-140608
Supplier : XY-GLOBAL

Inspection Date: 5th July, 2014
Inspector: Leo

Inspection only for: PO : XYND-140608 Item No.200-4690	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-4690	3000PCS	1% inspection	0pcs	No failure	3000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Product

[illegible]