

**Inspection Date:** 5<sup>th</sup> Apr, 2015  
**Inspector:** Leo

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY31CY012   | 18000PCS      | 1% inspection | 0pcs         | No failure          | 18000pcs        |

No failure.

**Dimension Inspection:**

No failure , below measurement report for reference

**Assembly Test:**

|            |  |
|------------|--|
| No failure |  |
|------------|--|

## Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. report

