

Inspection Report

Report No.: XYAK-150416
Supplier : XY-GLOBAL

Inspection Date: 20th May, 2015
Inspector: Leo

Inspection only for: PO . XYAK-150416 Item No. XY31AL013	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31AL013	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

Item	Spec	Actual	Unit	Pass	Fail	Remark
1	1.0000	1.0000	mm	100%	0%	
2	1.0000	1.0000	mm	100%	0%	
3	1.0000	1.0000	mm	100%	0%	
4	1.0000	1.0000	mm	100%	0%	
5	1.0000	1.0000	mm	100%	0%	
6	1.0000	1.0000	mm	100%	0%	
7	1.0000	1.0000	mm	100%	0%	
8	1.0000	1.0000	mm	100%	0%	
9	1.0000	1.0000	mm	100%	0%	
10	1.0000	1.0000	mm	100%	0%	
11	1.0000	1.0000	mm	100%	0%	
12	1.0000	1.0000	mm	100%	0%	
13	1.0000	1.0000	mm	100%	0%	
14	1.0000	1.0000	mm	100%	0%	
15	1.0000	1.0000	mm	100%	0%	
16	1.0000	1.0000	mm	100%	0%	
17	1.0000	1.0000	mm	100%	0%	
18	1.0000	1.0000	mm	100%	0%	
19	1.0000	1.0000	mm	100%	0%	
20	1.0000	1.0000	mm	100%	0%	
21	1.0000	1.0000	mm	100%	0%	
22	1.0000	1.0000	mm	100%	0%	
23	1.0000	1.0000	mm	100%	0%	
24	1.0000	1.0000	mm	100%	0%	
25	1.0000	1.0000	mm	100%	0%	
26	1.0000	1.0000	mm	100%	0%	
27	1.0000	1.0000	mm	100%	0%	
28	1.0000	1.0000	mm	100%	0%	
29	1.0000	1.0000	mm	100%	0%	
30	1.0000	1.0000	mm	100%	0%	
31	1.0000	1.0000	mm	100%	0%	
32	1.0000	1.0000	mm	100%	0%	
33	1.0000	1.0000	mm	100%	0%	
34	1.0000	1.0000	mm	100%	0%	
35	1.0000	1.0000	mm	100%	0%	
36	1.0000	1.0000	mm	100%	0%	
37	1.0000	1.0000	mm	100%	0%	
38	1.0000	1.0000	mm	100%	0%	
39	1.0000	1.0000	mm	100%	0%	
40	1.0000	1.0000	mm	100%	0%	
41	1.0000	1.0000	mm	100%	0%	
42	1.0000	1.0000	mm	100%	0%	
43	1.0000	1.0000	mm	100%	0%	
44	1.0000	1.0000	mm	100%	0%	
45	1.0000	1.0000	mm	100%	0%	
46	1.0000	1.0000	mm	100%	0%	
47	1.0000	1.0000	mm	100%	0%	
48	1.0000	1.0000	mm	100%	0%	
49	1.0000	1.0000	mm	100%	0%	
50	1.0000	1.0000	mm	100%	0%	
51	1.0000	1.0000	mm	100%	0%	
52	1.0000	1.0000	mm	100%	0%	
53	1.0000	1.0000	mm	100%	0%	
54	1.0000	1.0000	mm	100%	0%	
55	1.0000	1.0000	mm	100%	0%	
56	1.0000	1.0000	mm	100%	0%	
57	1.0000	1.0000	mm	100%	0%	
58	1.0000	1.0000	mm	100%	0%	
59	1.0000	1.0000	mm	100%	0%	
60	1.0000	1.0000	mm	100%	0%	
61	1.0000	1.0000	mm	100%	0%	
62	1.0000	1.0000	mm	100%	0%	
63	1.0000	1.0000	mm	100%	0%	
64	1.0000	1.0000	mm	100%	0%	
65	1.0000	1.0000	mm	100%	0%	
66	1.0000	1.0000	mm	100%	0%	
67	1.0000	1.0000	mm	100%	0%	
68	1.0000	1.0000	mm	100%	0%	
69	1.0000	1.0000	mm	100%	0%	
70	1.0000	1.0000	mm	100%	0%	
71	1.0000	1.0000	mm	100%	0%	
72	1.0000	1.0000	mm	100%	0%	
73	1.0000	1.0000	mm	100%	0%	
74	1.0000	1.0000	mm	100%	0%	
75	1.0000	1.0000	mm	100%	0%	
76	1.0000	1.0000	mm	100%	0%	
77	1.0000	1.0000	mm	100%	0%	
78	1.0000	1.0000	mm	100%	0%	
79	1.0000	1.0000	mm	100%	0%	
80	1.0000	1.0000	mm	100%	0%	
81	1.0000	1.0000	mm	100%	0%	
82	1.0000	1.0000	mm	100%	0%	
83	1.0000	1.0000	mm	100%	0%	
84	1.0000	1.0000	mm	100%	0%	
85	1.0000	1.0000	mm	100%	0%	
86	1.0000	1.0000	mm	100%	0%	
87	1.0000	1.0000	mm	100%	0%	
88	1.0000	1.0000	mm	100%	0%	
89	1.0000	1.0000	mm	100%	0%	
90	1.0000	1.0000	mm	100%	0%	
91	1.0000	1.0000	mm	100%	0%	
92	1.0000	1.0000	mm	100%	0%	
93	1.0000	1.0000	mm	100%	0%	
94	1.0000	1.0000	mm	100%	0%	
95	1.0000	1.0000	mm	100%	0%	
96	1.0000	1.0000	mm	100%	0%	
97	1.0000	1.0000	mm	100%	0%	
98	1.0000	1.0000	mm	100%	0%	
99	1.0000	1.0000	mm	100%	0%	
100	1.0000	1.0000	mm	100%	0%	

6. report

Our sales team

