

Inspection Report

Report No.: XYLA-150304
Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYLA-150304 Item No. XY31PC003	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC003	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY31PC003									
Item	Spec	Unit	Min	Max	Min	Max	Min	Max	Min
1	Length	mm	10.0	10.5	10.0	10.5	10.0	10.5	10.0
2	Inner Dia	mm	1.0	1.1	1.0	1.1	1.0	1.1	1.0
3	Outer Dia	mm	1.2	1.3	1.2	1.3	1.2	1.3	1.2
4	Weight	g	0.1	0.2	0.1	0.2	0.1	0.2	0.1
5	Material		PC		PC		PC		PC
6	Color		Black		Black		Black		Black
7	Surface		Smooth		Smooth		Smooth		Smooth
8	Finish		Mat		Mat		Mat		Mat
9	RoHS		Compliant		Compliant		Compliant		Compliant
10	Lead Time	Weeks	4		4		4		4
11	MOQ	pcs	1000		1000		1000		1000
12	Price	USD/pcs	0.01		0.01		0.01		0.01
13	Payment		T/T		T/T		T/T		T/T
14	Shipping		By Air		By Air		By Air		By Air
15	Incoterms		FOB		FOB		FOB		FOB
16	Warranty	Months	12		12		12		12
17	Return		Yes		Yes		Yes		Yes
18	Notes								

6. report

[illegible]

Safety is our serious job for our worker and engineer team

