

Inspection Report

Report No.: XYDA-150313

Supplier : XY-GLOBAL

Inspection Date: 8th Apr, 2015

Inspector: Leo

Inspection only for: PO . XYDA-150313 Item No. XY31CY031	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY031	35000PCS	1% inspection	0pcs	No failure	35000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Date	Product Type	Inspection Date
2015-04-08	XY31CY031	2015-04-08
Inspector	Inspector	Inspector
Leo	Leo	Leo
Inspection Result	Inspection Result	Inspection Result
PASS	PASS	PASS
XY31CY031		
1. 外观检查: 外观检查合格, 无缺陷。		
2. 尺寸检查: 尺寸检查合格, 符合规格。		
3. 功能检查: 功能检查合格, 符合规格。		
4. 包装检查: 包装检查合格, 符合规格。		
5. 结论: 合格。		

6. report

[illegible]