

Inspection Report

Report No.: XYNK-130824

Inspection Date: 15th Sep., 2013

Supplier: XY-GLOBAL

Inspector: LEO

Inspection only for:	<u>Inspection Result:</u>
PO: XYNK-130824 Item No. 3027819	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
3027819	1000PCS	100% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

[illegible]