

Inspection Report

Report No.: XYAN-150302

Supplier : XY-GLOBAL


Inspection Date: 1st Apr, 2015

Inspector: LEO

Inspection only for:	Inspection Result:
PO . XYBA-150302 Item No. XY21ZC088	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC088	6800pcs	7% inspection	0pcs	No failure	6800pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

[illegible]

Safety is our serious job for our worker and engineer team

