XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYAN-150305 **Inspection** Date:3th- Apr-, 2015
Supplier : **XY-GLOBAL** **Inspector:**LEO

Inspection only for:	Inspection Result:
PO . XYBA-150305 Item No. XY21ZC092	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC092	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product:

3. Product:

4. Product:

5. Product :



6. Inspection report:

□□□□□□□□□	□□□ □□□ □□□□□ □□□□□□ □□□□□□□□ □□□□□□ □□□□ □□□□□□ □□□□□ □□□□□□ □□□□□□□□ □□□□□□□ □□□ □□□□□□ □□□□□□ □□□□□□□□ □□□□□□□ □□□ □□□□□□□ □□□□□□ □□□□□ □□□□□□□ □□□□□□ □□□□□□□ □□□ □□□□□ □□□□□□ □□□□□□□□ □□□□□□□□ CNC □□□□□□ □□□□□□ CNC □□□□□ □□□□□□ CNC □□□□□ □□□□□□□
□□□□□□□	□□□□□□□□□□ AL6061 AL6065□ AL6063□ AL7075□ SUS304□ SUS303□ SUS316□ □□□ □□□
□□□□□□	□□□□□□□ □□□□ □□□ □□□□□□□
□□□□□□□ □□□□□□□□	□□□ □□□□ □□□□□□ □□□□□□ □□□□□□□□□ □□□□□□□ □□□□□□□ □□□□□□□ □□□□□□□ □□□□□□□ □□□□□
□□□□□□□□	□□□□□□□ □□□□□□□□ □□□□ □□ □□□□□□□ □□□□
□□□□□□□□ □□□□□□	CNC □□□□ □□□ □□□□□□ □□□ □□□□□□□ □□□□□ □□□□□ □□□ □□□□ □□□ □□□□ □□□ □□□ □□□□□□□ □□□□ □□□ □□□□□ □□□□□□ □□□□□□□□ □□□□□□□ □□□ □□□
□□□□ □□□□□	□□□□□□□□ □□□□□□ □□□□□□□ □□□□□ gague□ □□□□ □□□□□□□□ □□□□□□□ □□□□□□□□ □□□□□□□ □□□□□ □□□□□□□ □□□□□□□□ □□□□□ □□□□□□□ □□□□ □□□□□□□□□ □□□□ □□□□□□□□ □□□□□□□ □□□□□□□□□ □□□ □□□□□ □□□□□□□ □□□□ □□□ □□□□□□□ □□□□□□□ □□□□□□□□ □□□□□ □□□□□□□
□□□	□□□□□□□ □□□□
□□□□□□□ / □□□□□	+/- 0.01MM
□□□	T / T 50 □ □□□□□ □50 □□□□□□ T / T □□□□□ □□ □□□□□□ □□.
□□□□□□□ □□□□	CNC □□□□□□ □□□□□□□□ □□□□□□□ □□□□□□ □□□□□□ □□□□□□□□ □□□□□□□□ □□□□□□□ □□□□□ □□□□ □□□□□□ □□□□□ □□□□ □□□□□□□ □□□□□□□ □□□□□ □□□□□ □□□□□□ □□□□□□□□ □□□□□□□ □□□□□ □□□□ □□□ □□□□□□ □□□□□ □□□□ □□□□□□□
□□□□□	□□□□□□□□ □□□□□□□□□□ □□□□□□□□□ □□□□□ □□□□□□□ □□□□□□□□ □□□□ □□□□□ □□□□□□□□ □□□□ □□□□□□□ □□□□ □□□ □□□□□ □□□□□□□ □□□□□□□□ □□□□□□□□ □□ □□□□□□□ □□□□□□□□□□ □□□□□□□□ □□□□
□□□□□□□□	□□□□□ □□□□□
□□□□□	20-25 □□□ □□□□ T / T 50□ □□□□□□□ □□
□□□□□□□□ □□□□□□□	□□□ □□□□ □□□□□ □□□□□□ □□□□□□□□ □□□□□□□
1.Name: □□□□□□ □□□ OEM □□□□□□ □□□□ □□□ □□□□□ □□□□□□ □□□□□□□□ □□□□□□□	
2.Process: □□□□□ □□□□□□ □□□□□□□□ □□□□□□□ □□□□□ □□□□ □□□□□□□□□□	
3.Material: □□ AL6061 AL6065□ AL6063□ AL7075 POM □□□	
4.Surface □□□ □□□□□□ □□□□□□ □□□□□□ □□□□□□□ □□□□□□□□ □□□□□ □□□□□□ :□□□□□	
5.Tolerance: 0.01 -/+ □□□ □□□ □□ □□□□MM	
6 □□□□□□.Quality: 100□ □□□□□□□	
7.Specification: OEM □□□□□□□□ □□□□□ □□ □□□□ □□□□□	
8. □□□□□□□□ □□ □□□□□ 30-25 :□□□□□□□ □□□ □□□□.	
9. □□□□□□□ □□□□□□□□□ □□□□□□□□□□□ □□□□□ □□□□□ □□□□□□□ □□□□□□ □□□ :□□□□□□□ accessoried□ □□□□ □□□□□□□ □□□□□□□ □□□□□□□□ □□□□	
10. □□□□ □□□□□□□□□□ □□□□□□□ □□□□□□□□ :□□□□□□□□ AUSTRIAL□ □□□□□□ □□□□□□□□ □□□□□□□	
11. □□□□□: ISO 9001	
□□□□ □□□□□	
1. 10 □□□□□□ □□□□□ □□ □□□□□□ □□ □□□□	
2. □□□□□ □□□□□□ □□□□□ □□□□	
3. □□ kindls □□ sureface □□□ finishment □□ abailable	
4. □□□□□□□ □□□□□□□ □□□□□ □□□□	
5. □□□□□□ □□□□□ □□ □□□□□□□ □□□□	
6. □□□□□ □□□□	
7. □□□□□□ □□□□□ □□□□ □□□ □□□□□□□ □□ □□□□ □□□□□	
□□□□□□□□	
CNC □□□□□□□ □□□□□ □□□□ □□ :□□□□ □□□□□□ □□□□ □□□	
CNC □□□□□□□□ □□□□□□□ :□□□□□□□ □□□□□□ □□□□ □□□	
CNC □□□□□ □□□□□□ □□□□ □□□: ISO9001	
CNC □□□□ □□□□□□ □□□□□□ :□□□□ □□□□□□ □□□□ □□□	
□□□□ CNC □□□□□□ □□□□ □□□ OEM	

Safety is our serious job for our worker and engineer team