

Inspection Report

Report No.: XYCY-150228
Supplier : XY-GLOBAL

Inspection Date: 20th Mar, 2015
Inspector: Leo

Inspection only for: PO . XYCY-150228 Item No. XY31CY003	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY003	40000PCS	1% inspection	0pcs	No failure	40000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing




2. Product



3. Product



4 Product



Inspection Report		Product Name		Inspection Date		Inspector	
XYCY-150228	XYCY-150228	XYCY-150228	XYCY-150228	2015.03.20	2015.03.20	Leo	Leo
1. General Inspection: The product is in good condition, no defects found. 2. Dimensional Inspection: The product dimensions are within the specified tolerance. 3. Material Inspection: The material is of good quality, no impurities found. 4. Surface Inspection: The surface is smooth, no scratches or discoloration found. 5. Packaging Inspection: The packaging is secure, no damage found.							

5. Product:

6. report

[illegible]