

Inspection Report

Report No.: XYCY-150308
Supplier : XY-GLOBAL

Inspection Date: 3rd Apr, 2015
Inspector: Leo

Inspection only for: PO : XYCY-150308 Item No. XY31CY010	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY010	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. report

