

# Inspection Report



Report No.: XYF-130804  
Supplier : XY-GLOBAL

Inspection Date:1<sup>th</sup> Sep-, 2013  
Inspector:LEO

|                                                                 |                                   |
|-----------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYK-130804      Item No.100-23-870 | <u>Inspection Result:</u><br>PASS |
|-----------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size     | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| 100-23-870  | 30000Set      | 100% inspection | 0pcs         | No failure          | 30000Set        |

|                                                      |
|------------------------------------------------------|
| <b>Appearance Inspection :</b>                       |
| No failure.                                          |
| <b>Dimension Inspection:</b>                         |
| No failure , below measurement report for reference. |
| <b>Assembly Test:</b>                                |
| No failure                                           |
| <b>Inspection Summary</b>                            |
| The inspection sample plan is 100% inspection.       |

|                                                                                     |                                                                                      |
|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Digital photo records :                                                             |                                                                                      |
|   |   |
| 1. Packing                                                                          | 2. Product:                                                                          |
|  |  |
| 3. Product:                                                                         | 4. Product:                                                                          |
|  |  |
| 5. Product :                                                                        | 6. inspection reports                                                                |

[illegible]