

Inspection Report

Report No.: XYBA-140918

Supplier: XY-GLOBAL


Inspection Date: 14th Oct., 2014

Inspector: LEO

Inspection only for:	Inspection Result:
PO: XYBA-140918 Item No. XY21ZC012	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC012	1000PCS	7% inspection	0pcs	No failure	1000pcs

Appearance Inspection:
No failure,
Dimension Inspection:
No failure, below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records:	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product:	6. Inspection report:

[illegible]