

Inspection Report

Supplier : XY-GLOBAL

Inspection Date: 2th July, 2014

Inspector: Leo

Inspection only for: PO . XYSK-140608 Item No. XY31SY008	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY008	15000PCS	1% inspection	0pcs	No failure	15000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

[illegible]