

Inspection Report

Report No.: XYKB-140524
Supplier: XY-GLOBAL

Inspection Date: 20th Jun, 2014
Inspector: Leo

Inspection only for: PO : XYKB-140524 Item No. XY72YM020	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM020	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report	Product Type	Inspection Date
XY72YM020	XY72YM020	2014.06.20
Inspector	Inspector	Inspector
Leo	Leo	Leo

Inspection Result: PASS

Inspection Summary: The inspection sample plan is 100% inspection.

Inspection Details: The inspection was performed on 2014.06.20. The inspection result is PASS. The inspection summary is that the inspection sample plan is 100% inspection.

Inspection Report: The inspection report is a document that records the results of the inspection. It includes the product type, inspection date, inspector, and inspection result. The inspection result is PASS.

Inspection Summary: The inspection summary is a brief overview of the inspection. It includes the product type, inspection date, inspector, and inspection result. The inspection result is PASS.

Inspection Details: The inspection details are the specific results of the inspection. They include the number of defects found, the number of samples inspected, and the number of samples passed. The inspection result is PASS.

5. Product:

6. Dimensions report:

[illegible]