

Inspection Report


Report No.: XYBA-141116
Supplier : XY-GLOBAL

Inspection Date: 19th Dec., 2014
Inspector:LEO

Inspection only for: PO . XYBA-141116 Item No. XY21ZC036	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC036	6000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	 2 / 148 / 2
5. Product :	6. Inspection report:

[illegible]