

Inspection Report

Report No.: XYGA-150314

Supplier : XY-GLOBAL

Inspection Date: 18th Apr-, 2015

Inspector:LEO

Inspection only for: PO . XYGA-140314 Item No. XY21ZC054	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC054	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:

[illegible]

233

5. Product :

6. Inspection report:

[illegible]