

Inspection Report

Report No.: XYBA-141127

Supplier : XY-GLOBAL

Inspection Date: 24th Dec-, 2014

Inspector:LEO

Inspection only for: PO . XYBA-141127 Item No. XY21ZC044	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC044	3000Pcs	7% inspection	0pcs	No failure	3000Pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

[illegible]

6. Inspection report:

