

Inspection Report

Report No.: XYF-130810
Supplier : XY-GLOBAL

Inspection Date: 5th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYF-130810 Item No.230459	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
230459	20000Set	100% inspection	0pcs	No failure	20000Set

Appearance Inspection :

No failure.

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. inspection reports

