

## Inspection Report

Report No.: XYNK-140611

Inspection Date: 9<sup>th</sup> July, 2014

Supplier : XY-GLOBAL

Inspector: Leo

|                                                             |                            |
|-------------------------------------------------------------|----------------------------|
| Inspection only for:<br>PO . XYNK-140611    Item No.1400289 | Inspection Result:<br>PASS |
|-------------------------------------------------------------|----------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 1400289     | 1000PCS       | 1% inspection | 0pcs         | No failure          | 1000pcs         |

### Appearance Inspection :

No failure,

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure

### Inspection Summary

The inspection sample plan is 100% inspection.

### Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Product:

[illegible]