XY-GLOBAL XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYKB-140523
Supplier : **XY-GLOBAL**

Inspection Date: 17th Jun, 2014
Inspector: Leo

Inspection only for:	Inspection Result:
PO . XYKB-140523 Item No. XY72YM019	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM019	1000PCS	1% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:

6. Dimensions report:

[illegible]	[illegible] OEM [illegible]
[illegible]	[illegible] ADC12[illegible] A380 [illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	CNC [illegible] CNC [illegible]
[illegible]	[illegible] gague[illegible]
[illegible]	[illegible]
[illegible] / [illegible]	+/- 0.01MM
[illegible]	T / T 50 [illegible] 50 [illegible] T / T [illegible].
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	20-25 [illegible] T / T 50[illegible]
[illegible]	[illegible]
1.Name: [illegible] OEM [illegible]	
2.Process: [illegible]	
3.Material: [illegible] ADC12[illegible] A380 [illegible]	
4.Surface [illegible] :[illegible]	
5.Tolerance: 0.01 -/+ [illegible]MM	
6 [illegible].Quality: 100[illegible]	
7.Specification: OEM [illegible]	
8. [illegible] 30-25 :[illegible].	
9. [illegible] :[illegible] accessoried [illegible]	
10. [illegible] :[illegible] AUSTRIAL[illegible]	
11. [illegible]: ISO 9001	
[illegible]	
1. 10 [illegible]	
2. [illegible]	
3. [illegible] kindls [illegible] sureface [illegible] finishment [illegible] abailable	
4. [illegible]	
5. [illegible]	
6. [illegible]	
7. [illegible]	
[illegible]	
[illegible] :[illegible]	
[illegible] :[illegible]	
[illegible]: ISO9001	
[illegible] :[illegible]	
[illegible] OEM	