

Inspection Report

Report No.: XYSK-140621
Supplier: XY-GLOBAL

Inspection Date: 15th July, 2014
Inspector: Leo

Inspection only for: PO . XYSK-140621 Item No. XY31SY019	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY019	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Date	15/07/2014	Inspector	Leo	Product Name	XY31SY019	Inspection Result	PASS
PO No.	XYSK-140621	Item No.	XY31SY019	Lot No.	15070101	Quantity	10000

Inspection Method: 100% inspection

Inspection Location: XY Electronics Technology Co., Ltd

Inspection Time: 15/07/2014

Inspection Result: PASS

Inspector: Leo

Company: XY Electronics Technology Co., Ltd

6. report

1.Name: 2.Process: 3.Material: 4.Surface 5.Tolerance: 6 7.Specification: 8. 9. 10. 11. 	1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11.
---	---