

## Inspection Report

Report No.: XYI-140320  
Supplier : XY-GLOBAL

Inspection Date: 17<sup>th</sup> Apr, 2014  
Inspector: Leo

|                                                        |                                   |
|--------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO : XYI-140320 Item No.142089 | <u>Inspection Result:</u><br>PASS |
|--------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 142089      | 40000PCS      | 1% inspection | 0pcs         | No failure          | 40000pcs        |

### Appearance Inspection :

No failure.

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure

### Inspection Summary

The inspection sample plan is 100% inspection.

### Digital photo records :




1. Packing



2. Product



3. Product




4 Product



5. Product:



6. Product:



7. Product:

8. Report:

[illegible]