

Inspection Report


Report No.: XYFA-140905
Supplier : XY-GLOBAL

Inspection Date: 5th Oct., 2014
Inspector: LEO

Inspection only for: PO . XYFA-140905 Item No. XY21ZC062	<u>Inspection Result:</u> PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC062	5000pcs	7% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

[illegible]