

## Inspection Report

Report No.: XYDS-140620

Inspection Date: 19<sup>th</sup> July, 2014

Supplier : XY-GLOBAL

Inspector: Leo

|                                                                |                                   |
|----------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYDS-140620    Item No.101-20-481 | <u>Inspection Result:</u><br>PASS |
|----------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 101-20-481  | 10000PCS      | 1% inspection | 0pcs         | No failure          | 10000pcs        |

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

**Digital photo records :**



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Product

[illegible]