

Inspection Report

Report No.: XYFD-130804

Inspection Date: 3th Sep-, 2013

Supplier: XY-GLOBAL

Inspector: LEO

Inspection only for: PO . XYFD-130804	Item No. 400-10-071	Inspection Result: PASS
--	---------------------	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-071	6000Set	100% inspection	0pcs	No failure	6000Set

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product :

