

Inspection Report

Report No.: XYN-131117

Inspection Date: 10th Dec-, 2013

Supplier : XY-GLOBAL

Inspector: KEN

Inspection only for: PO . XYN-131117 Item No.XY-MST-035	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-035	35000PCS	1% inspection	0pcs	No failure	35000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]