

Inspection Report

Report No.: XYN-131111
Supplier : XY-GLOBAL

Inspection Date: 4th Dec-, 2013
Inspector:KEN

Inspection only for: PO . XYN-131111 Item No.XY-MST-027	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-027	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

[illegible]