

Inspection Report

Report No.: XYDN-140607

Inspection Date: 1st July, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO : XYDN-140607 Item No.240010	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
240010	1200PCS	1% inspection	0pcs	No failure	1200pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product

[illegible]