

Inspection Report

Report No.: XYDW-140615

Supplier: XY-GLOBAL

Inspection Date: 12th July, 2014

Inspector: Leo

Inspection only for: PO : XYDW-140615 Item No. XY33AH009	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH009	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report

Customer: XYDW-140615	Product Type: XY33AH009	Inspection Date: 12/07/2014	Inspector: Leo
Part: XY33AH009	Lot: XY33AH009	Quantity: 50000	Unit: PCS
Inspection Item: XY33AH009	Inspection Method: 100% Inspection	Inspection Result: PASS	Inspection Status: OK

XY Electronics Technology Co., Ltd

12/07/2014

Leo

6. report

[illegible]