

Inspection Report

Report No.: XYKB-140515

Inspection Date: 11th Jun, 2014

Supplier: XY-GLOBAL

Inspector: Leo

Inspection only for:	Inspection Result:
PO: XYKB-140515 Item No. XY72YM011	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM011	3000PCS	1% inspection	0pcs	No failure	3000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Date	Product Name	Inspection Date	Inspector
2014.06.11	XY72YM011	2014.06.11	Leo
Part No.	Lot No.	Inspection Result	Inspector
XY72YM011	140515	Pass	Leo
Inspection Item	Inspection Method	Inspection Result	Inspector
Appearance	Visual	Pass	Leo
Dimension	Caliper	Pass	Leo
Material	Visual	Pass	Leo
Quantity	Count	Pass	Leo
Assembly	Visual	Pass	Leo
Storage	Visual	Pass	Leo
Transportation	Visual	Pass	Leo
Final Inspection	Visual	Pass	Leo

5. Product:

6. Dimensions report:

[illegible]