

Inspection Report

Report No.: XYNK-130827

Inspection Date: 20th Sep., 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for:	<u>Inspection Result:</u>
PO : XYNK-130827 Item No. 3010796	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
3010796	500PCS	100% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. Product:

