

Inspection Report

Report No.: XYSK-140610
Supplier: XY-GLOBAL

Inspection Date: 2th July, 2014
Inspector: Leo

Inspection only for: PO . XYSK-140610 Item No. XY31SY010	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY010	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing



2. Product



3. Product



4. Product




5. Product:

6. report

[illegible]