

Inspection Report

Report No.: XYSL-130525
Supplier : XY-GLOBAL

Inspection Date: 27th Jun, 2013
Inspector: Leo

Inspection only for: PO : XYSL-130525 Item No. XY11SL015	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL015	10000PCS	5% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing 	2. Product 
3. Product 	4 Product 
5. Product:	6. The test report

[illegible]