

Inspection Report

Report No.: XYNK-130810

Supplier : XY-GLOBAL


Inspection Date: 2th Sep-, 2013

Inspector: LEO

Inspection only for:	<u>Inspection Result:</u>
PO : XYNK-130810 Item No. 400-10-454	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-454	5000PCS	100% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
 	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

[illegible]