

□□□□□□ □□□□ □□□□□□ □□□□□□□□□□ □□□□ □□□□ □□□□ □□□□□□ □□□□□ □□□□

Inspection Report

Report No.: XYD-130703
Supplier : XY-GLOBAL

Inspection Date: 10th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130703 Item No.XY-956400	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-956400	800PCS	5% inspection	0pcs	No failure	800pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.


Digital photo records :



1. Packing



2. Product




3. Product



4 Product



5. Product:



6. Product:

[illegible]